◆User:

Monday, 2/25/2008 7:34:01 AM

Kim Johnston

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

Type

S.O. No. :

: WEARSHOE

Job Number

Drawing Name

Estimate Number

: 37584

: D353513

P.O. Number

: 12737

Part Number

This Issue Prsht Rev.

: 2/25/2008

Drawing Number

- D3535 REV B

: NC

Project Number

: N/A

First Issue

: //

: SMALL /MED FAB **Drawing Revision**

Previous Run

: B

: 36423

Material Due Date

: 3/6/2008

Qty: Each

Written By

Checked & Approved By

Comment

: Est Rev:A New Issue 07-02-15 JLM

Est Rev:B As per Rev B 07-08-31 JLM Verified By:EC

Additional Product

Job Number: -1. 1. 1. 1.



Seq. #

1 5 TY 115

alten by

Machine Or Operation:

Description:

1.11.0 15 128 mg r

M304S20GA

304/316 .040 Sheet



Comment: Qty .:

0.8930 sf(s)/Unit

17.8605 sf(s)

304/316 .040 Sheet

(M304S20GA)

106748

Total:

8-5-55

2.0

Attended town

without & App. 11.



Comment: FLOW WATER JET

1-Cut as per_Dwg D3535

Dwg Rev: Prog Rev:_ 8-2-35



2-Deburr if necessary

B 8-2-25

3.0

INSPECT PARTS AS THEY COME OFF MACHINE



B 8-3-32



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

4:0 Sec 2 . 12.

SECOND CHECK

.... Comment: SECOND CHECK

5.0

BRAKE NC

NC BRAKE



Comment: NC BRAKE

1-Form on Brake as per Dwg D3535 using Jigs DT8261and DT8326

2-Form joggle as per Dwg D3535 using Jig DT8158Identify as D3535-13

Dart Aerospace Lt

W/O:		WORK ORDER CH	IANGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	<i>*</i>				-3-		
				`			
Part No	:	PAR #: Fault Category:	NCR: Yes	(W) DQ	A: <u>\</u>	〕 Date: <u> (</u>	38/03/1

QA: N/C Closed: ____ Date: _

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC	Corrective Action Section B		Verification	Approval	Approval				
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspecto			
•				- 1940							
							0				
			*								

Date: Monday, 2/25/2008 7:34:01 AM User: Kim Johnston **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: WEARSHOE Part Number: D353513 Job Number: 37584 Job Number: Seq. #: Machine Or Operation: Description: 6.0 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP POWDER COATING POWDER COATING M106442 Comment: POWDER COATING Powder Coat Grey Sandtex (Ref: 4.3.5.6) as per QSI 005 4.3 INSPECT POWDER COAT/CHEMICAL CONVERSION 08-03. Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: FO 03-03-13 Comment: FINAL INSPECTION/W/O RELEASE 08/03 2008/3/13 Job Completion . co jagaren la Maria . . .


Dart Ae	rospace	Ltd		* .							
W/O:				WO	RK ORDER	R CHANGE	S				
DATE	STEP		PRO	OCEDURE CHÂN	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
*			*								
					:			e1.			
		- 1									
Part No	:		PAR #:	Fault Categ	ory:		NCR: Yes	No DQ	A:	Date:	
			٠	-			QA:	N/C Close	d:	_ Date: _	
NCR:			V	WORK ORDE	R NON-CC	NFORMAN	ICE (NC	R)			

NCR:			WORK ORD	ER NON-CONFORMANO	CE (NCR)			
		Description of NC		Corrective Action Section B		Verification	Approval	A
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	Approval QC Inspecto
				•				
					÷ (ā)			
	10							
			<u>-</u>					-
	-							
					÷	9		
				•				
			¥					

W/O:		WORK ORDER CHANGES				,	
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
v							
·							

Part No:	PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:
			QA: N/C C	losed:	Date:

NCR:			WORK ORDE	ER NON-CONFORMAN	CE (NCR)			
	T	Description of NC		Corrective Action Section B		Verification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
	,				3			
				2)				



W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
16							
						L.	

Part No:	PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:
			QA: N/C	losed:	Date:

		WORK ORDE	ER NON-CONFORMAN	CE (NCR)			
	Description of NC		Corrective Action Section E	3	Verification	Approval	Approval
STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
	4						
	STEP	STED Description of NC	STEP Description of NC Section A Initial	STEP Description of NC Section A Initial Action Description	STEP Description of NC Section A Initial Action Description Sign &	STEP Description of NC Section A Initial Action Description Sign & Verification Section C	STEP Description of NC Section A Portion Description Section B Section C Chief Eng

W/O:		WORK ORDER CH	IANGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
190							
					+		

Part No:	PAR #:	Fault Category:	NCR: Yes No	DQA:	Date:
			QA: N/C	Closed:	Date:

NCR:			WORK ORDI	ER NON-CONFORMANO	CE (NCR)			
		Description of NC		Corrective Action Section B		Verification	Approval	Approval QC Inspector
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	
							i	
		4						
						:		
							-	

B

DART

AEROSPACE PORT HADLOCK,

USA,

NC.

DRAWING NO.

SHEET

4 OF 7 **₹**

SCALE


07.04.17

WEARSHOE

hz:ho:La REE ENSER

22.500 19,000 9.500 6.000 2.000 1.885 DETAIL A **≠**0.188 (TYP 3 PLS)

D3535-31F FLAT PATTERN



D3535-31 BEND DETAIL

UNCONTROLLED COPY SUBJECT TO AMENDMENT SHOP COPY WITHOUT NOTICE ENGINEERING RETURN TO

돺

DOCUMENT IS


Copyright © 2006 by DART AEROSPACE USA, INC.

PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.


유

COPIED

- 1) MATERIAL: AISI 304/316 SS SHEET PER AMS 5513 OR AMS 5524,
- 20 GAUGE (0.038 THICK)
 (REF DART SPEC M304S20GA)
 2) FINISH: POWDER COAT GREY SANDTEX (4.3.5.6) PER
 QSI 005 4.3
- 3) PART IS SYMMETRICAL ABOUT Q
 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- ALL DIMENSIONS ARE IN INCHES
- BREAK ALL SHARP EDGES TO 0.010 MAX
- IDENTIFY WITH DART P/N USING WHITE FINE POINT PAINT MARKER
- 8) SEE PAGE 7 FOR DETAILS AND SECTION



D3535-33F FLAT PATTERN



Dart Ae	rospace	Ltd							
W/O:		,	WC	ORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #:	Fault Cate	gory:N	CR: Yes	No DQ	A:	Date:	I
					QA: N	/C Close	d:	_ Date: _	
NCR:			WORK ORDI	ER NON-CONFORMANC	E (NCR	2)			
		Description of NC		Corrective Action Section B		Verific	eation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti		Chief Eng	QC Inspector

\$

DART

AEROSPACE PORT HADLOCK,

NO.

D3535 DRAWING NO.

SHEET

Çī


SCALE 윾

1:10

DATE

07.04.17

WEARSHOE



DETAIL A

UNCONTROLLED COPY SUBJECT TO AMENDMENT SHOP COPY ENGINEERING WITHOUT NOTICE RETURN TO

1) MATERIAL: AISI 304/316 SS SHEET PER AMS 5513 OR AMS 5524. 20 GAUGE (0.038 THICK)
(REF DART SPEC M304S20GA)
FINISH: POWDER COAT GREY SANDTEX (4.3.5.6) PER
QSI 005 4.3

- PART IS SYMMETRICAL ABOUT &

캎

DOCUMENT IS

Copyright © 2006 by DART AEROSPACE USA, INC.


PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

PURPOSE

윢

COPIED

- TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- ALL DIMENSIONS ARE IN INCHES
- BREAK ALL SHARP EDGES TO 0.010 MAX
- IDENTIFY WITH DART P/N USING WHITE FINE POINT PAINT MARKER
- 8) SEE PAGE 7 FOR DETAILS AND SECTION



د آټوز

b2 ho 60

THE MAN

	c -	
	<u>^^</u>	
	c, j	•
2	03535-37 BEND DETA	NL .

17.

P ---

W/O:		WORK ORDER C	HANGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		·					
Part No	:	PAR #: Fault Category:′	NCR: Yes	No DQ	A:	Date:	

QA: N/C Closed: _____ Date: _____

NCR:			WORK ORDE	R NON-CONFORMANCE (NCR)							
		Description of NC		Corrective Action Section	В	Varification	ication tion C Approval Chief Eng	Approval QC Inspector			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C					
								:			
		<u> </u>									
	ate & initial all										

W/O:			WORK ORDER C	HANGES			····	
DATE	STEP	PRO	OCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								,
Part No	o:	PAR #:	Fault Category:	NCR: Yes	No DQ	A:	_ Date: _	


QA: N/C Closed: ____ Date: ____


NCR: WORK ORDER NON-CONFORMANCE (NCR)								
	T	Description of NC		Corrective Action Section B		Verification	Approval Chief Eng	Approval QC Inspector
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C		
-								
				·				
								·
		4					¥ .	



A2-10-10

RELEASED





Ī

DOCUMENT

Copyright © 2006 by DART AEROSPACE USA, INC.
IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

SHOP COT Y R1.620 RETURN TO RETURN TO ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING ENGINEERING NOTICE WITHOUT NOTICE WITHOUT NOTICE WITHOUT NOTICE WITHOUT NOTICE	P
SECTION C-C	

CB CB	DRAWN BY	DART AEROSPACE USA, INC.
CHECKED ,,,	APPROVED/	DRAWING NO. REV.
¥		D3535 SHEET 7 OF
DATE		TITLE
07.04.17		WEARSHOE

W/O:		WORK ORDER CHANG	ES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #: Fault Category:	_ NCR: Yes	No DQ	A:	Date:	
			QA: I	N/C Close	d:	_ Date: _	

NCR:			WORK ORD	ER NON-CONFORMAN	CE (NCR)			, , , , , , , , , , , , , , , , , , , ,
		Description of NC		Corrective Action Section B			Annroval	Annroval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approva QC Inspecto
		*						
		·						
			-					

DART AEROSPACE LTD	Work Order:	375 84	
Description: WEAR SHOE	Part Number:	03555-13	
Inspection Dwg: D3S3S-(3 Rev: R		Page 1 of 1	

FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawin g Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Ø ,188	1.005 - 200.1	ì			·	
,300	400	.302	x			
.300	4010	302	×		10	
1,885	4/010	1.892	76			
3,000	+/- 010	3.000	*	·		
5,650	4/010		*			
9.150	4/- 1010	9.150	≭ £			
14.066	4- 010	14.066	yk_			
289.81	4/010	18.983	*		1	
23.900	4/010	23, 900	*	-		
27,400	-/010	27,400	*			•
29.400	7- 00	29.400	*		-	
39.900	+1010	35.°CE	*		•	•
5,00	4030	5,00	*			•
8.00	Y036		*			
14.00	4030	14.05	*			
30.00	4030	26.00	*			
	·			-		
						-
		ς.				
					.1	
						2

Messured by: K	Audited by:	Prototype Approval:	Prototype Approval:		
Date: 8-2-3	Date:	Date:			

Rev Date	Ch	·			
Jale	Change			Revised by	Approved
_A	New Issue			KJ/JLM	

